

WS HAMPSHIRE CAPABILITIES

Machine	Description	Travel X Axis (in)	Travel Y Axis (in)	Travel Z Axis (in)	Table Size	Axis	Coolant
Haas TM2	CNC Machining Center	40"	16"	16"	57" X 10"	4	Mister
Haas TM2	CNC Machining Center	40"	16"	16"	57" X 10"	3	Mister
Haas VF2SS	CNC Machining Center	30"	16"	20"	40" X 19"	3	YES
Haas VF2SS	CNC Machining Center	30"	16"	20"	40" X 19"	3	YES
Haas VF3SSYT	CNC Machining Center	40"	26"	25"	67" X 28"	4	YES
Haas VF6SS	CNC Machining Center	64"	32"	30"	78" X 31"	4	YES
Haas VF6 (Standard)	CNC Machining Center	64"	30"	30"	66" X 36"	3	NO
Haas VF9	CNC Machining Center	84"	40"	30"	90" x 39"	4	YES
Fadal 6030	CNC Vertical Mill	60"	30"	30"	60" X 30"	3	NO
Fadal 8030	CNC Vertical Mill	80"	30"	30"	77" X 32"	3	NO
Haas GR510	CNC Router	120"	60"	6"	59" X 120"	3	NO
Haas GR712	CNC Router	142"	84"	6"	84" X 142"	3	NO

Machine	Description	Max. Turn OD	Max. OD Turn Lgth	Max. Bore. Dia.	Max Bore Length	Axis	Coolant
Haas ST30SSY	CNC Turning Center	16.5"	21"	18"	10.5"	4	YES
Mazak QT20	CNC Turning Center	10"	17"	9"	7.5"	2	NO
Okuma LB25	CNC Turning Center	16"	22"	11"	11"	2	YES
Okuma LB15	CNC Turning Center	12"	14"	8"	7"	2	YES
Okuma LB15	CNC Turning Center	12"	14"	8"	7"	2	YES
Okuma Cadet	CNC Turning Center	11"	10"	6"	5"	2	YES

Machine	Description	Max. Turn OD	Max. OD Turn Lgth	Steady Rest	Max Bore Length	Mister Available
LeBlond Gap Bed Lathe	Manual Lathe	48"	33"	NO	24"	Yes
LeBlond 3 or 4 jaw chuck Lathe	Manual Lathe	21"-23"	Aprox 42"	NO	24"	Yes
Lansing 3 jaw chuck lathe	Manual Lathe	30"	72" W/T.S.	NO	24"	Yes

Machine	Description	Travel X Axis	Travel Y Axis	Travel Z Axis	Table Size
BridgePorts (3)	Manual Knee Mill	36"	12"	5"	9" X 49"

Machine	Description	Max Cutting Width	Max Sheet Length	Max Sheet Thickness
Schelling FK8 430 CNC Saw	CNC Panel Saw	169"	N/A	6.1"
Holzma HPP 380 CNC Saw	CNC Panel Saw	149"	N/A	3.75"